



ELECTRICALLY ACTUATED DISC CLUTCH EKS

CLUTCH IS DESTINATED FOR EQUIPMENTS WITH NUMEROUS SWITCHING AND WITH DEMAND TO SHORTEN WORKING CYCLES AND TO INCREASE PRODUCTION SPEED WITH THE REASON TO BOOST WORKING CAPACITY OF MACHINES. CLUTCH IS USED NAMELY IN PACKING, TEXTILE AND FOOD EQUIPMENTS. WORKS ONLY IN SURROUNDINGS WITHOUT LUBRICATION.



MAIN TECHNICAL DATA AND DIMENSIONS (MM)

Size		4	6.3	10	16	25	
Nom. torqueM _n Nm 40 Stat, torque M _{max}		63	100	160	250		
			48	75	120	185	290
Current		А	1.24	1.63	1.92	2.37	2.62
Input		W	29.7	39.1	46	56.9	63
Diameters	А		144	158	182	210	235
	В		132	145	166	195	218
	C		55	62	75	90	100
	D		38	44	56	66	70
	d ₁ MIN		19	22	25	30	32
	MAX		28	35	42	48	55
	E		47	53			
Oia	F	mm	93	104	112	134	150
	G		119	132	149	178	200
	Н		125	140	160	190	214
	Ī		3x5.1	3x6.1	3x8.1	3x8.1	3x10.1
	J		8.5	10			
	K		11.5	15	20	20	25
	M		2xM5	2xM6	2xM6	2xM8	2xM10
	N		4x6.5	4x6.5	4x8.5	4x8.5	4x8.5
	0		58	65	78	93.5	103.5
Lengths	L		28	32	36	40	44
	L ₁		3	4	4	4	4
	L ₂		38.5	44			
	L ₃		31	36	40	44	48
	P_1		3	4	4	5	5
	P ₂	mm	7	8	8	9	10
	R		7.2	7.7			
	S		5.15	6.15	6.65	6.65	7.15
	S1		2.15	2.15	2.65	2.65	3.15
	Т		8	8	8	10	10
	U		4.5	5.4	-	3.5	
	Χ		0.3	0.3	0.3	0.3	0.4
Moment of	inertia	1/2					
armature		Kgm ²	1.84.10-3	3.57.10-3	7.2.10-3	15.2.10-3	28.66.10-3
jacket			9.6.10-4	2.06.10-3	2.83.10-3	6.47.10-3	12.645.10-3
Max. revolution		min-1	3000	3000	2600	2200	1800
Veight		kg	2.5	3.75			
- 5		7.0					

Clutch EKS consists of driving part, driven part and fixed magnetic body. Clutch jacket forms driving part. Friction material without asbestos is placed on friction surface to improve friction quality. Two tapped holes are placed on face side, out of friction area to enable disassembling. Armature with riveted shaped spring forms driven part. In the spring there are 3 holes to be fixed on driven part of equipment. Spring enables after switch-off department of armature plate from clutch jacket and ensures its position in off position. Exciting coil is sealed in fixed magnetic body. Control voltage is 24 V d.c. Control voltage is conducted to free wires in magnetic body. 4 holes are made in flange of body to grip to the fixed part of machine.

ORDERING DATA

- size and type
- number of pieces
- bore and key slot in clutch jacket
- voltage
- climatic conditions



750 53 PŘEROV • CZECH REPUBLIC TEL. 0641/23 36 30, 23 36 33 FAX 0641/20 31 82, 20 31 60



Quality system certified according to DIN ISO 9001